

1135 Wireless Siren

July 2010

Hardware Update

Effective June 2010, all 1135 Wireless Sirens are being manufactured with Level E hardware.

Updated Hardware

Wireless Siren

The 1135 hardware has been enhanced by the addition of a capacitor to improve communication with the XTL control panel during the period when the siren is turned on.

Previously, some 1135 Wireless Sirens could not receive the siren off command from the panel especially if they were located far from the panel. This was because electrical noise from the running siren caused a reduction in wireless communication capabilities.

Note: The internal operation of the 1135 siren circuit will always automatically turn off the siren after 15 minutes.

An installed 1135 Wireless Siren that can not be immediately turned off by the XTL control panel may be moved closer to the XTL to improve communication. If this fails to remedy the situation, then the 1135 could be returned to DMP for an update.

Receiving the New Hardware

To update to level E, return any 1135 PCB to DMP and simply indicate "Update to Latest Hardware Level" on the 5-digit RMA tag. The update will be done as a Warranty Repair at no charge, regardless of when the 1135 was purchased. If a wireless siren is returned for other repair needs, this update will be automatically performed as standard repair procedure. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

