

1135 Wireless Siren

September 2017

Corrected Audible Functionality

We have identified and corrected an issue with the 1135 Wireless Siren when it is used with panel bell action set to either temporal or pulse. The audible will not sound correctly when used in either of those programmed settings. There are no audible issues when panel bell action is set to steady.

The problem affects any 1135s shipped between June 28, 2017 and August 31, 2017. Affected units will have a serial number between 15239700 and 15240988. If you have received any of these units, you may send them in and they will be replaced with a corrected unit free of charge. All units shipped as of September 1, 2017 have been corrected and operate as expected.

Updating 1135 Wireless Sirens

If you have any questions or would like to request an update to your affected units, please contact DMP Customer Service or Technical Support at 1-800-641-4282.



Figure 1: 1135 Wireless Siren