

1100X Feature Update May 2007

Version 104 Software Update

Effective June 2007, all 1100X Wireless Receivers are being manufactured with Version 104 (5/1/07) software. This version is an update from the Version 102 (9/21/06) software previously shipped and contains new features.

Features

Wireless Expanders

The 1100X Wireless Receiver now supports the 1114 Wireless Four-Zone Expander, 1116 Wireless Relay Output, 1117 Wireless LED Annunciator and 1118 Wireless Remote Indicator Light for use with the XR100 and XR500 Series Command Processor™ panels.

To support these wireless transmitters, the following updates are also required:

- XR100 or XR500 Series Command Processor panels must have Version 119 or higher
- Remote Link must have Version 1.36 or higher to allow remote programming for the new wireless expanders.

Ordering the New Software

To update the software in an existing 1100X, return the receiver to DMP and simply indicate "Update to Version 104" on the 6-digit RMA tag. The update will be done as a Warranty Repair at no charge, regardless of when the receiver was purchased. If a receiver is returned for other repair needs, this update will be done automatically as a standard part of the repair. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

