

XR100 and XR500 Series

June 2007

Version 119 Software Update

Effective June 2007, all XR100 and XR500 Series Command Processor panels are being manufactured with version 119 (6/25/07) software. This version is an update from the version 119 (5/4/07) software previously available and contains updated operation.

Updated Operation

Flash Update Operation

This software update is a revision to the internal operations that perform a flash update on the panel. The issue was discovered on one of the internal DMP factory inspections and has not been reported from any field installations. No XR100/XR500 panel operating features have been revised.

When using version 119 (5/4/07) to flash update a panel, in most cases, the flash update would be successful. In a very rare instance, the flash update could be unsuccessful causing the panel to not operate. If a panel has already been successfully updated to version 119 (5/4/07), then there is no additional action required.

Version 119 (6/25/07) should be used to update panels going forward in the place of version 119 (5/4/07).

Obtaining the New Software

XR100 and XR500 Series software update Version 119 (6/25/07) is available for download free of charge on the DMP Dealer Direct Website at <http://dmp.com/dealer>.