

## 1139 Software Update August 2008

### Version 100 Software Update

Effective August 2008, all 1139 Wireless Bill Trap transmitters are being manufactured with Version 100 (8/15/08) software. This new version will begin shipping immediately. This version is an update from the Version 100 (2/11/08) software previously shipped and contains updated operation.

### Updated Operation

#### Battery Life Improved

The new Version 100 (8/15/08) software further improves the battery life of the 1139 Bill Trap. Most 1139 Bill Traps manufactured since February of 2008 operate with the normal 1 year battery life expectancy. However, in a few cases, the processor operation could shorten battery life. This typically occurred when the transmitter was unable to communicate with the 1100 Series receiver such as a period of time that the cash tray would be in a vault. An indication of trouble would be a low battery or an unexpected missing message at the keypad. This has been corrected in version 100 (8/15/08).

### Receiving New Software

To update the software for an existing 1139, return the bill trap to DMP and simply indicate "Update to Current Version" on the RMA tag. The update will be done as a Warranty Repair at no charge, regardless of when the bill trap was purchased. If a bill trap is returned for other repair needs, this update will be done automatically as a standard part of the repair. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282. In addition to the software update, new batteries will be supplied when the unit is returned to you.

