

1100 Series Wireless Receivers November 2008

Version 106 Software Update

Effective November 2008, all 1100D, 1100DH, 1100DI, 1100X, 1100XH and 1100XI Wireless Receivers are being manufactured with Version 106 (10/31/08) software. This version is an update from the following software versions previously shipped:

- § 1100D and 1100X Version 105 (10/22/07)
- § 1100DH and 1100XH Version 105 (2/11/08)
- § 1100DI and 1100XI Version 105 (1/31/08)

Features

1100R Wireless Repeater

The 1100 Series Wireless Receivers now support the 1100R Wireless Repeater. The 1100R Wireless Repeater provides increased communication range by forwarding messages from the transmitter to the wireless receiver. Up to eight repeaters can be installed on a wireless system. The repeater is powered from a 12 VDC power supply and includes a 24-hour battery backup. Using the on-board LEDs, the 1100R Wireless Repeater provides built-in survey capability to allow for single-person installations, eliminating the requirement for an external survey kit.

Ordering the New Software

To update the software in an existing 1100 Series Wireless Receiver, return the receiver to DMP and simply indicate "Update to Version 106" on the 6-digit RMA tag. The update will be done under warranty at no charge, regardless of when the receiver was purchased. If a receiver is returned for other repair needs, this update will be done automatically as a standard part of the repair. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

