

XR5SL August 2009

Firmware Update

Effective September 2009, all XR5SL Slave Communicator panels are being manufactured with Version 106 (8/17/09) firmware. This version is an update from the Version 106 (2/12/09) firmware previously shipped and contains updated operation.

Note: This update does not apply to the XR5FC Fire Alarm Control panel.

Compatibility

Version 106 firmware can only be used in XR5 panels using Revision 7 Level L printed circuit boards.

Updated Operation

Zone Restorals

The XR5SL slave communicator version 106 (8/17/09) no longer requires a sensor reset before a zone restoral is sent to the receiver. The requirement to not send restorals until the fire alarm control (FACP) is manually reset applies to the FACP and not the slave communicator.

After a fire alarm occurs, the fire alarm relay output of the FACP should hold the XR5SL zone in the shorted condition until a manual reset of the FACP is performed.

Ordering New Firmware

New firmware PROMs may be obtained from buy.dmp.com or by calling DMP Customer Service at 1-800-641-4282 and ordering XR5SL/UPDATE.