

1100R Wireless Repeater May 2010

Version 200 Update

Effective June 2010, all 1100R Wireless Repeaters are being manufactured as Version 200 (5/12/10) software. This version is an update from the Version 106 (12/18/09) software previously shipped and contains new features and updated operation.

New Features

1135 Wireless Siren/9000 Series Wireless Keypads

The 1100R Version 200 now supports the 1135 Wireless Siren and 9060/9063 Wireless keypads when used with the XTL Version 105.



Updated Operation

Input DC Fail Time

When the DC power from the Model 376 transformer is low or removed, the time that must expire before the repeater's zone open messages is sent to the wireless receiver is now three (3) minutes to comply with the upcoming 1100R UL Commercial Fire Listing.

The 1100R repeater now transmits an open zone after three (3) minutes if unplugged from the wall or AC power is not present or low.

Previously, the repeater would not transmit the open zone for one (1) hour.

Ordering the New Software

To update the software in an existing 1100R Wireless Repeater, return the repeater to DMP and simply indicate "Update to Version 200" on the 6-digit RMA tag. This update will be done automatically as a standard part of the repair. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

