

7073ANEE Software Update April 2010

Version 303 Software Update

Effective April 2010, all 7073ANEE keypads are being manufactured with version 303E (3/18/10) software. This version is an update from the Version 303E (9/28/09) previously shipped and contains updated operation.

Updated Operation

LCD Display

Incorrect characters do not display at the end of the exit delay if the door strike relay is left on because of a door output schedule.

Previously, these characters would appear in the display and the door strike relay had to be turned off to clear the display to normal.

Obtaining the New Software

To receive the updated firmware, return the keypad to DMP and simply indicate "Update to Latest Firmware" on the 5-digit RMA tag. The update will be done as a Warranty Repair at no charge, regardless of when the keypad was purchased. If a keypad is returned for other repair needs, this update will be done automatically as a standard part of the repair. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

REPAIR AUTHORIZATION

DO NOT SEND METAL CABINETS WITH CIRCUIT BOARD

100491

POST CLEARLY WITH SHIPMENT TO: DMP

Company: ALARM CO NAME

Address: ADDRESS

City: _____ State: _____ Zip: _____

Model No.: MODEL SN

Installation Site: _____

Describe Problem: UPDATE TO LATEST FIRMWARE

Preferred return shipping method: _____

FOR DMP USE ONLY

Received: _____ By: _____ Code: _____

Replaced: _____ In-Circuit Test: _____ Functional Test: _____

Parts Replaced: _____

PCB Housing Box

Final Test: _____ By: _____

Shipped: _____ By: _____

Date Entry: _____ By: _____

KEEP THIS STICK FOR YOUR RECORDS

Repair Voucher

Model No.: 100491

Installation Site: SN

Date Returned: _____ By: _____