

1145 Series Wireless Key Fob September 2014

Version 107 Software Update

Effective September 2, 2014, all 1145 Series Wireless Key Fobs are being manufactured with Version 107 (6/13/13) software.

Updated Operation

Stored Message

1145 Series Wireless Key Fobs, on rare occasions, may have sent a button press when no button was being pressed. This could occur if a button had been pressed just as the key fob was returning to the range of the wireless receiver. The button press may have been incorrectly stored by the key fob to be sent with the next communication to the wireless receiver such as a battery test.

Obtaining the New Software

To update, return any older 1145 Series Wireless Key Fob to DMP and simply indicate "Update to Latest Version 107 Software" on the 6-digit Repair Authorization tag. The update will be done as a Warranty Repair at no charge, regardless of when the key fob was purchased. If you need Repair Authorization tags contact DMP Customer Service at 1-800-641-4282.

Software Version
The software version of an 1145 is found by removing the back cover of the key fob.



REPAIR AUTHORIZATION

DO NOT SEND METAL CABINETS WITH CIRCUIT BOARD

157668

PRINT CLEARLY THIS IS YOUR RETURN SHIPPING DOCUMENT.

Company ALUM CO NAME
Address ADDRESS
City _____ State _____ Zip _____
Model No. MODEL Installation Site _____ S/N _____
Describe Problem _____
UPDATE TO LATEST SOFTWARE

Preferred return shipping method _____

FOR DMP USE ONLY

Received _____ By _____ Code _____
Repair Test _____ In-Circuit Test _____ Functional Test _____
Parts Replaced _____ By _____ Code _____

PCB Housing Box

Final Test _____ Shipped _____ By _____
Data Entry _____ By _____

KEEP THIS STUB FOR YOUR RECORDS

Repair Voucher _____
Model No. _____ 157668
Installation Site _____