

## 734N/734N-WiFi Wiegand Interface Modules November 2013

### Version 100 Software Update

Effective November 21, 2013 all 734N and 734N-WiFi Wiegand Interface Modules are being manufactured with Version 100 (11/16/13) software. Version 100 (11/16/13) will begin shipping as current inventory of 734N and 734N-WiFi Wiegand Interface Modules is depleted which is expected to occur mid December 2013.

### Updated Operation

#### Zone 2 Bypass

When ACTIVATE ZONE 2 BYPASS? is set to YES in the Access Options Programming menu, 734N and 734N-WiFi modules now correctly ignore changes in the state of the door contact connected to Zone 2 during the Zone 2 Bypass Time. Previously, a change in the state of the door contact (door opened) that occurred during the Bypass Time was sent to the panel after the Bypass Time expired.

### Obtaining the New Software

To update to the latest software, return the 734N or 734N-WiFi Wiegand Interface Module to DMP and simply indicate "Update to Latest Version Software" on the RMA tag. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

REPAIR AUTHORIZATION

DO NOT SEND METAL CABINETS WITH CIRCUIT BOARD

157668

PRINT CLEARLY, THIS IS YOUR RETURN SHIPPING DOCUMENT.

Company BLANK CO. NAME

Address ADDRESS

City \_\_\_\_\_ State \_\_\_\_\_ Zip \_\_\_\_\_

Model No. MODEL S/N \_\_\_\_\_

Installation Site \_\_\_\_\_

Describe Problem UPDATE TO LATEST SOFTWARE

Preferred return shipping method \_\_\_\_\_

FOR DMP USE ONLY

Received \_\_\_\_\_ By \_\_\_\_\_ Code \_\_\_\_\_

Bench Test \_\_\_\_\_ In-Circuit Test \_\_\_\_\_ Functional Test \_\_\_\_\_

Repaired \_\_\_\_\_ By \_\_\_\_\_ Code \_\_\_\_\_

Parts Replaced \_\_\_\_\_ By \_\_\_\_\_ Code \_\_\_\_\_

PCB  Housing  Box

Final Test \_\_\_\_\_ By \_\_\_\_\_

Shipped \_\_\_\_\_ By \_\_\_\_\_

Data Entry \_\_\_\_\_ By \_\_\_\_\_

KEEP THIS STUB FOR YOUR RECORDS

Repair Voucher

Model No. 157668

Installation Site \_\_\_\_\_