

Remote Link and System Link January 2014

Version 1.68 Software Update

Effective January 31, 2014, all Remote Link and System Link software is being manufactured as Version 1.68 (1/31/14). If your current Remote Link or System Link software is previous to Version 1.46, update to Version 1.59 before updating to 1.68 (1/31/14).

Features

XR550E Series Encryption

Communication programming for XR550E Series Control Panels using Version 104 or higher software now includes an option for 256-bit AES Encryption. This feature is only available for panels communicating to an SCS-104 Receiver Line Card with Version 102 or higher software.

Disarm Disable

The Disarm Disable option in Zone Information programming is now available for Model 1103 Wireless Universal Transmitters. A zone with Disarm Disable selected will not send a zone tripped message to the wireless receiver when the panel is disarmed. Supervision, low battery and tamper messages are always sent. This feature is supported by 1103 Wireless Universal Transmitters operating with Version 107 (1/21/14) or higher software installed with the following panels:

- XR150/XR350/XR550 Series Control Panels Version 104 or higher software
- XR500/XR100 Series Control Panels Version 212 (1/24/14) or higher software
- XT Series Panels Version 117 or higher software

Updated Operation

Profiles in Account Groups

When profiles were created for XR100/XR500 panels using the Account Groups module in Remote Link Version 1.67 (3/22/13) or higher, the Arm and Disarm options were combined and displayed using a single checkbox. When checked, only Disarm Authority was enabled for that profile in the panels of the group. Remote Link Version 1.68 (1/31/14) correctly displays separate checkboxes for Arm and Disarm.

Easy Arm

When configuring a profile for XR150/XR350/XR550 Series Control Panels, the Easy Arm option could not be enabled using Remote Link Version 1.67 (3/22/13) or higher. If the Easy Arm option was checked to enable and programming was sent to the panel, the option was incorrectly disabled in the panel by Remote Link.

Zone Status

When requesting Zone Status from an XT Series Control Panel, Remote Link Version 1.66 (12/20/13) or higher would randomly request the status of a zone multiple times. When this occurred, multiple status entries for that zone were displayed.

Obtaining the New Software

Remote Link and System Link Version 1.68 (1/31/14) updates are available for download free of charge on the DMP Dealer Direct Website at <http://dmp.com/dealer>.