

iComSL Series

July 2017

Version 125 Firmware Update

Version 125 (5/19/217) firmware is now available for download on the DMP Dealer Direct Website at <http://dmp.com/dealer>.

Effective July 6, 2017, all iComSL Universal Network Communicators will be manufactured with updated Version 125 (5/19/217) firmware. Updated units will begin shipping as current inventory is depleted.

Updated Functionality

Communication Failure Output

The Communication Failure Output feature is now available on iComSL Universal Network Communicators. This feature ensures that a communication failure output triggers if a check-in message is not sent to the receiver within a specified number of minutes.

To access this programming option, navigate to **OUTPUT OPTIONS**. When the **COM FAIL OUT** screen displays, enter the output number you would like to trigger.

Obtaining the New Firmware

New iComSL Universal Network Communicators with this feature can be ordered (after current inventory is depleted) by contacting DMP Customer Service at 1-800-641-4282 or by visiting buy.dmp.com.