

FEATURE UPDATE

Version 100 (4/1/20) Date Code Update

Effective April 9th, 2020, the 503INT International Power Supply is being manufactured and shipped with updated Version 100 (4/1/20) firmware.

Features

Improved Zone Reporting

Previously, when AC power failure occurred and the battery was good, the 503INT would occasionally incorrectly report a faulted state for the Zone 2 Output Trouble. With updated Version 100 firmware, this issue no longer occurs.

Obtaining the New Firmware

To order the new 503INT International Power Supply with updated Version 100 (4/1/20) firmware, contact DMP Customer Service at 1.866.266.2826.