

## TECHNICAL UPDATE

### Version 201 (4/24/20) Update

Effective April 30th, 2020, all XTLplus and XTLtouch Series panels are being manufactured with updated Version 201 (4/24/20) Firmware.

### Improvements

#### 1144 Key Fob LED Feedback Improvement

Previously, there was an issue in XTLplus and XTLtouch panels where 1144 Key Fobs would not give consistent LED feedback when used to arm/disarm the panel. Updated Version 201 (4/24/20) resolves this issue.

#### 1135 Siren Delay Improvement

Updated Version 201 (4/24/20) resolves an issue where the 1135 Wireless Siren delays sounding by up to 45 seconds and also delays reverting back to a normal state after an alarm is canceled by up to 45 seconds. With updated Version 201 (4/24/20), this issue no longer occurs and the siren responds normally.

### Obtaining the New Firmware

XTL Series firmware updates are available, free of charge, on Dealer Admin ([dealer.securecomwireless.com](http://dealer.securecomwireless.com)) or [DMP.com/Dealer\\_Direct](http://DMP.com/Dealer_Direct).