

TECHNICAL UPDATE | APRIL 2021

Version 106 (4/26/21) Date Code Update

Effective April 26, 2021, all 1100T Series Wireless Translators are being manufactured with Version 106 (4/26/21) firmware.

Improved Keyfob Programming

Previously, when DMP keyfob zone numbers were programmed before non-DMP device zone numbers, the non-DMP device zones were not polled correctly. This issue is resolved with Version 106 (4/26/21) date code release.

If you have a version prior to Version 106 (4/26/21) and need to add 1144 keyfobs, add them to a zone after the non-DMP devices.

Obtaining the New Firmware

New 1100T Series Wireless Translators Version 106 (4/26/21) can be ordered by contacting DMP Customer Service at 1-866-266-2826 or by visiting buy.dmp.com.