



## FEATURE UPDATE

### Version 193 (1/14/20) Update

Effective February 10th, 2020, all XR Series Panels are being manufactured with updated Version 193 (1/14/20) firmware.

### Features

#### TCP Connection Sequence Randomization

Updated Version 193 randomizes the sequence number for all new TCP connections. This eliminates the possibility of XR panels being flagged by vulnerability scanners for predictable TCP sequences.

#### Remote Key Programming

Updated Version 193 firmware resolves an issue where user codes would be scrambled and unusable when imported from Entré into the panel. This issue was caused if the panel remote key was entered incorrectly when the panel was created in Entré.

#### Remote Programming Enhancement

Previously, when wireless zones were remotely programmed using a cellular or dialer connection, it could take up to 15 minutes or resetting the panel for the newly programmed zones to start working. Updated Version 193 firmware resolves this issue.

### Obtaining the New Firmware

XR Series firmware updates are available, free of charge, at [dealer.securecomwireless.com](http://dealer.securecomwireless.com) or [DMP.com/Dealer\\_Direct](http://DMP.com/Dealer_Direct).