

## 1139 Wireless Bill Trap May 2013

### Version 107 Software Update

Effective May 3, 2013, all 1139 Wireless Bill Traps are being manufactured with Version 107(4/24/13) software. This software contains the following feature.

### Feature Update

#### Improved Battery Life

The communication process of a wireless bill trap has been improved to further battery life. During the period when the bill trap has been stored in a safe or vault causing a loss of communication with the receiver, the number of times the bill trap attempts to find the wireless receiver is reduced to conserve the battery.

### Obtaining the New Software

To update, return any older 1139 Wireless Bill Trap to DMP and simply indicate "Update to Latest Software" on the RMA tag. The update will be done as a Warranty Repair at no charge, regardless of when the bill trap was purchased. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

**REPAIR AUTHORIZATION**

DO NOT SEND METAL CABINETS WITH CIRCUIT BOARD

157668

PRIME CLEARANCE THIS IS YOUR RETURN SHIPPING DOCUMENT.

Company ALBANY CO. NAME  
Address ADDRESS  
City \_\_\_\_\_ State \_\_\_\_\_ Zip \_\_\_\_\_  
Model No. MODEL S/N \_\_\_\_\_  
Installation Site \_\_\_\_\_  
Describe Problem UPDATE TO LATEST SOFTWARE

Preferred return shipping method \_\_\_\_\_

FOR DMP USE ONLY

Received \_\_\_\_\_ By \_\_\_\_\_ Code \_\_\_\_\_  
Bench Test \_\_\_\_\_ In-Circuit Test \_\_\_\_\_ Functional Test \_\_\_\_\_  
Repaired \_\_\_\_\_ By \_\_\_\_\_ Code \_\_\_\_\_  
Parts Replaced \_\_\_\_\_ By \_\_\_\_\_ Code \_\_\_\_\_

PCB  Housing  Box

Final Test \_\_\_\_\_ By \_\_\_\_\_  
Shipped \_\_\_\_\_ By \_\_\_\_\_  
Data Entry \_\_\_\_\_ By \_\_\_\_\_

KEEP THIS STUB FOR YOUR RECORDS

Repair Voucher  
Model No. \_\_\_\_\_ S/N 157668  
Installation Site \_\_\_\_\_