

1121 Wireless PIR October 2009

Version 106 Update

Effective October 2009, all 1121 Wireless PIRs are being manufactured as Version 106 (10/1/09) software. This version is an update from the Version 106 (2/18/09) software previously shipped and contains updated operation.

Updated Operation

Battery Life Improved in High Traffic Areas

The software of the 1121 PIR has been improved to increase battery life in high traffic areas, such as a school. The 1121 waits until motion is not detected for a full two minutes before allowing the PIR to detect any new movement. Previously the 1121 could trip in less than 30 seconds. This improvement should have impact in systems with high traffic areas. The improvement in lower traffic systems such as residential will not be as noticeable.

Ordering the New Software

To update the software in an existing 1121 Wireless PIR, return the transmitter to DMP and simply indicate "Update to Version 106" on the 6-digit RMA tag. This update will be done automatically as a standard part of the repair. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

The image shows a repair authorization tag with the following handwritten information:

- Model No.: 100491
- Company: ALBERTA CO. NAME
- Address: ADDRESS
- City: _____ State: _____
- Model No.: MODEL No.
- Installation Site: _____
- Describe Problem: UPDATE TO LATEST FIRMWARE
- FOR DMP USE ONLY
- Received: _____ By: _____
- Inspected: _____ By: _____
- Field Adjustment: _____ By: _____
- Field Test: _____ By: _____
- Shipping: _____ By: _____
- Date Entry: _____
- Repair Number: 100491
- Installation Site: ON
- Date Returned: _____