

## 734 Interface Module June 2009

### Version 100 Software Update

Effective June 2009, all 734 Wiegand Interface Modules are being manufactured with Version 100 (6/23/09) software. This version is an update from the Version 100 (11/26/08) software previously shipped and contains updated operation.

### Updated Operation

#### Two Card Reader

When two card readers are wired in parallel to the Wiegand input of the 734 module and a card is read at both readers simultaneously, the 734 module will continue to operate but the card reads will not be processed.

Previously, when simultaneous card reads had occurred, the 734 would not allow any additional card reads, which then required the 734 power to be cycled to resume normal operations.

This issue did not occur when two readers were used but cards were read at different times from each reader.

### Ordering the New Software

To update the software for an existing 734, return the module to DMP and simply indicate "Update to Current Version" on the RMA tag. The update will be done as a Warranty Repair at no charge, regardless of when the module was purchased. If a module is returned for other repair needs, this update will be done automatically as a standard part of the repair. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

