

## 1139 Hardware Update

February 2008

### Hardware Update

Effective February 2008, all 1139 Wireless Bill Traps are now manufactured with updated Level B hardware.

### Updated Hardware


#### Low Battery Detection

New Level B hardware for the 1139 Wireless Bill Trap corrects an issue where a low battery condition occurred after 4 – 6 months of normal operation. The Level B hardware provides the expected 1 year of battery life for the 1139.

### Obtaining Hardware Level B

To update, return any older Level A 1139 Bill Traps to DMP and simply indicate "Update to Latest Hardware Level B" on the RMA tag. The update will be done as a Warranty Repair at no charge, regardless of when the 1139 was purchased. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

The 1139 was originally released for sale in March of 2007.



Level Indicator

