

1142 Software Update April 2008

Version 102 Software Update

Effective April 2008, all 1142 Wireless 2-Button Holdup Transmitters are being manufactured with Version 102 (3/25/08) software. This is an update from Version 101 (2/19/07) software previously shipped and contains a new feature.

Feature

Button Press

The 1142 Wireless 2-Button Holdup Transmitter now requires a one-half (1/2) second press of both buttons for a Panic Alarm to be communicated to the 1100 Series Receiver. Previously, a one (1) second press was required.

In addition, the LED feedback of the message sent is instantaneous. Previously, a 2½ second delay occurred before the LED flashed.

Ordering the New Software

To update the software in an existing 1142, return the transmitter to DMP and simply indicate "Update to Current Version" on the RMA tag. If a transmitter is returned for other repair needs, this update will be done automatically as a standard part of the repair. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

