

**TECHNICAL UPDATE | FEBRUARY 2019****Version 1.4.4 Update**

Effective February 14th, 2019, all SCS-VR Virtual Receiver Software will be manufactured with Version 1.4.4 (1/29/19) software.

**Updated Functionality****Check-in Tables**

SCS-VR Version 1.4.4 (1/29/19) addresses an issue with Check-in Tables. When a panel went missing in SCS-VR, only the primary database was updated. If SCS-VR switched to the secondary database before the panel restored, SCS-VR would generate additional S16 messages. This issue has been resolved.

**Server ID and UUID Mismatch**

SCS-VR Version 1.4.4 (1/29/19) addresses an issue that would occur with mismatched Server IDs and the UUID. If the primary and secondary databases had different Server IDs for the UUID, the groups in the secondary database were disabled. This issue has been resolved.

**Message Types**

SCS-VR Version 1.4.4 (1/29/19) addresses an issue with “Panel IP Change” and “Unrecognizable Message” types. These messages were not being removed from the Messages window after the message expiration time, causing a backlog of messages in the SCS-VR database. This issue has been resolved.

**Obtaining the New Software**

Contact the Software Support Team in DMP Technical Support at 1.888.436.7832 for information on updating to SCS-VR Version 1.4.4.