

1100 Series Wireless Receivers

June 2015

Version 203 Update

Effective June 15, 2015, all 1100 Series Wireless Receivers are being manufactured with Version 203 (11/26/14) firmware. The updated firmware will begin shipping as current stock is depleted which is estimated to occur mid July 2015.

Features

1164 Wireless Synchronized Smoke Detector

1100 Series Wireless Receivers with Version 203 (11/26/14) firmware now support the synchronized sounder operation of the soon to be released Model 1164 Wireless Synchronized Smoke Detector.



Obtaining the New Firmware

To update to the latest firmware, return the receiver to DMP and simply indicate "Update to latest version firmware" on the 6-digit Repair Authorization Tag. The update will be done as a Warranty Repair at no charge, regardless of when the receiver was purchased. If a receiver is returned for other repair needs, this update will be automatically performed as standard repair procedure. If you need Repair Authorization Tags, contact DMP Customer Service at 1-800-641-4282.

When a customer service order includes a Model 1164 and an 1100 Series wireless receiver, the receiver will automatically be shipped with Version 203 (11/26/14) firmware.

When purchasing a new receiver, to take advantage of the new 1164 support before current inventories are depleted, contact DMP Customer Service and request a receiver with Version 203 (11/26/14) firmware.

