

## 738Z Z-Wave Interface Module

July 2013

### Firmware Update

Effective July 18, 2013, all 738Z Z-Wave Interface Modules are being manufactured and shipped with Version 101 (4/26/13) firmware.

### Feature

#### Graphic Keypad Support

The 738Z Z-Wave Interface Module now supports the new graphical Z-Wave menus of the 7800 Series Graphic Keypad in systems that have been updated to the following:

- 7800 Series Graphic Keypad new Version 101 software
- XT30/XT50 and XTL Series Control Panel new Version 115 software
- XR150/XR350/XR550 Series Control Panel new Version 101 software

For more information on this feature refer to the 7800 Series Graphic Keypad Version 101 (6/28/13) Technical Update (TU-0683).

### Updated Operation

#### Z-Wave Lock Improvements

Improvements have been made to increase the reliability of the following lock functions:

##### Lock Control using the Virtual Keypad App

On occasion, the Virtual Keypad App would display a "Not Responding" status message for a lock when a user attempted to control the lock. Version 101 (4/26/13) prevents this issue by providing a higher priority to lock messages.

##### Disarming using a Z-Wave lock

Previously, when attempting to disarm the system by entering a user code at a Z-Wave lock, at times, the system would fail to disarm. Improvements made in Version 101 (4/26/13) allow users to reliably disarm the system from a lock.

It is recommended that XT30/XT50 Control Panels where a 738Z is installed be updated to new Version 115 software to benefit from this updated operation. XR150/XR350/XR550 Control Panels should be updated to new Version 101 software.

### Obtaining the New Firmware

To update to the latest firmware, return the 738Z Z-Wave Interface Module to DMP and simply indicate "Update to Latest Version Software" on the RMA tag. The update will be done as a Warranty Repair at no charge. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

