TECHNICAL UPDATE

1139 Wireless Bill Trap May 2012

Version 107 Software Update

Effective May 24, 2012, all 1139 Wireless Bill Traps are being manufactured with Version 107 software. This software contains the following updated operation.

Updated Operation

Enhanced Noise Immunity

The 1139 Wireless Bill Traps now provide enhanced immunity to radio frequency (RF) noise. Environmental RF noise occurs when AC electrical devices are turned on and off. Previously, RF noise could cause the bill trap to intermittently activate the wireless radio in preparation for radio communication reducing battery life.

Low Battery testing

The 1139 Wireless Bill Trap now reports a low battery condition in a more timely manner by automatically testing for a low battery every four hours.

Previously, the low battery test was based on a set number of trips to trigger a low battery report.

Obtaining the New Software

To update, return any older 1139 Wireless Bill Trap to DMP and simply indicate "Update to Latest Version 107 Software" on the RMA tag. The update will be done as a Warranty Repair at no charge, regardless of when the key fob was purchased. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.



