

738Z Z-Wave Interface Module March 2012

Firmware Update

Effective March 26, 2012, all 738Z Z-Wave Interface Modules are being manufactured with Version 100 (03/22/12) firmware. This version contains updated operation.

Updated Operation

Z-Wave Door Locks

The 738Z now briefly ignores messages from other Z-Wave devices while adding a Z-Wave lock to the system. Once the lock has been successfully added, the 738Z resumes the processing of other messages.

Previously, if the 738Z received a message from another Z-Wave device while adding a lock, the 738Z occasionally failed to complete the communication with the lock causing it to be added as an "Other" device type instead of a "Lock" type.

Obtaining the New Software

To update to the latest software, return the 738Z Z-Wave Interface Module to DMP and simply indicate "Update to Latest Version Software" on the RMA tag. The update will be done as a Warranty Repair at no charge. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

REPAIR AUTHORIZATION

DO NOT SEND METAL CABINETS WITH CIRCUIT BOARDS

157668

PRINT CLEARLY THIS IS YOUR RETURN SHIPPING DOCUMENT.

Company ALARM CO. NAME

Address ADDRESS

City _____ State _____ Zip _____

Model No. MODEL S/N _____

Installation Site _____

Describe Problem UPDATE TO LATEST SOFTWARE

Preferred return shipping method _____

FOR DMP USE ONLY

Received _____ By _____ Code _____

Bench Test _____ In-Circuit Test _____ Functional Test _____

Repaired _____ By _____ Code _____

Parts Replaced _____ By _____ Code _____

☐ PCB ☐ Housing ☐ Box ☐

Final Test _____ By _____

Shipped _____ By _____

Date Entry _____ By _____

KEEP THIS STUB FOR YOUR RECORDS

Repair Voucher

Model No. 157668

Installation Site _____