TECHNICAL UPDATE

SCS-VR

July 2010

Version 1.3.1 Software Update

Effective July 2010, all SCS-VR Virtual Receivers are being manufactured as Version 1.3.1 (7/2/10). This version contains new features added to obtain the ANSI/UL Listing for UL 1076 Proprietary Burglar Alarm Units.

New Features

Version Display

SCS-VR now displays the software version and software type (Enterprise or Professional) in the Setup Console.

SCS-VR Supervision

When SCS-VR is running on two different computers for a UL 1076 installation, the Setup Console displays a warning window to the user after 30 seconds when an SCS-VR is stopped or communication is lost between the computers.

Database Connection Supervision

When SCS-VR is running on two different computers for a UL 1076 installation and they are sending/receiving database information from a third computer, the Setup Console now informs the user with a warning window within 30 seconds when the database connection has failed.

Build Number

The build number no longer appears in the Automation tab as it was for internal use only.

Ordering New Firmware

SCS-VR Version 1.3.1 update will be automatically provided to dealers who have previously purchased an SCS-VR license and are current with their SCS-VR support agreement.

