

1145, 1146 and 1147 Software Update September 2008

Version 100 Software Update

Effective September 2008, all 1145, 1146 and 1147 Wireless Key Fobs are being manufactured with Version 100 (8/18/08) software. This version is an update from the Version 100 (3/21/08) software previously shipped and contains updated operation.

Updated Operation

Battery Life Improved

The new Version 100 (8/18/08) software further improves the battery life of the 1145, 1146 and 1147 Wireless Key Fobs. Most 1145, 1146 and 1147 Key Fobs manufactured since March of 2008 operate with the normal 2 year battery life expectancy. However, in a few cases, the processor operation could shorten battery life. This typically occurred when the key fob was unable to communicate with the 1100 Series receiver. An indication of trouble would be a low battery or an unexpected missing message at the keypad if the keyfob was supervised.

Receiving New Software

To update the software for an existing 1145, 1146 or 1147, return the key fob to DMP and simply indicate "Update to Current Version" on the RMA tag. The update will be done as a Warranty Repair at no charge, regardless of when the key fob was purchased. If a key fob is returned for other repair needs, this update will be done automatically as a standard part of the repair. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282. In addition to the software update, new batteries will be supplied when the unit is returned to you.

