TECHNICAL UPDATE

1145, 1146 and 1147 Software Update

March 2008

Version 100 Software Update

Effective April 2008, all 1145, 1146 and 1147 Wireless Key Fobs are being manufactured with version 100 (3/21/08) software. This version is an update from the version 100 (8/16/06) software previously shipped and contains updated operation.

Updated Operation

LED Acknowledgement

The 1145, 1146 and 1147 Wireless Key Fobs now always receive acknowledgement from the receiver and turn on the LED every time a button is pressed.

Previously, the key fob would occasionally not display the LED acknowledgement.

Button Press

The 1145, 1146 and 1147 Wireless Key Fobs now always send a button press to the receiver.

Previously, the key fobs would occasionally not send the button press requiring a second press.

Ordering the New Software

To update the software in an existing 1145, 1146 or 1147, return the key fob to DMP and simply indicate "Update to Current Version" on the RMA tag. The update will be done as a Warranty Repair at no charge, regardless of when the key fob was purchased. If a key fob is returned for other repair needs, this update will be done automatically as a standard part of the repair. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

