

## 1161 and 1162 Software Update August 2007

### Version 100 Software Update

Effective September 2007, all 1161 and 1162 Wireless Smoke Detectors are being manufactured with version 100 (8/20/07) software. This version is an update from the version 100 (8/14/06) software previously shipped and contains updated operation.

### Updated Operation

#### Installing Batteries

The 1161 or 1162 Wireless Smoke Detectors now wait twelve (12) seconds after installation of batteries to begin normal operation. This power up delay is to allow the smoke detector alarm and low battery circuitry to initialize.

Previously, when batteries were installed, an alarm may have been generated. The alarm would restore when a Sensor Reset was performed.

This issue did not occur when batteries were replaced one at a time and could only occur after both were removed.

### Ordering the New Software

To update the software in an existing 1161 or 1162, return the smoke detector to DMP and simply indicate "Update to Current Version" on the RMA tag. The update will be done as a Warranty Repair at no charge, regardless of when the detector was purchased. If a detector is returned for other repair needs, this update will be done automatically as a standard part of the repair. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

