

iCOMsL Software Update June 2007

Version 201 Software Update

Effective June 2007, all iCOMsL Network Routers are being manufactured with Version 201 (5/31/07) software. This version is an update from the Version 200 (5/1/06) software previously shipped and contains updated operation.

Updated Operation

Output Operation

The switched ground outputs of the iCOMsL output now operate properly when assigned to follow a zone.

Previously, when network communication had failed and the iCOMsL zone was shorted or opened, the output would follow the zone but the actions of turning on and then off could have been delayed.

Obtaining the New Software

iCOMsL software update version 201 (5/31/07) is available for download free of charge on the DMP Dealer Direct Website at <http://dmp.com/dealer>.