

867 Firmware Update May 2007

Version 100 Firmware Update

Effective June 2007, all 867 LX-Bus Addressable Notification Modules are being manufactured with version 100 (4/10/07) firmware. This version is an update from the version 100 (2/6/98) firmware previously shipped and contains updated operation.

Updated Operation

Odd Numbered Zones Show Trouble

An 867 notification module connected to the LX-Bus of an XR500 Series panel and programmed with an odd numbered zone for module supervision, such as 523, now always indicates the correct zone status.

Previously, the 867 could occasionally indicate a trouble condition for the status of an odd numbered zone even though the zone status was normal. All even numbered addresses have always worked properly.

Obtaining New Firmware

To receive the updated firmware, return the module to DMP and simply indicate "Update to Latest Firmware" on the 6-digit RMA tag. The update will be done as a Warranty Repair at no charge, regardless of when the module was purchased. If a module is returned for other repair needs, this update will be done automatically as a standard part of the repair. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

