

1145 Series Key Fobs

May 2012

Version 107 Software Update

Effective May 10, 2012, all 1145 Series Key Fobs are being manufactured with Version 107 (4/16/12) software. This version contains the following feature.

Feature

Wireless Receiver Communication

Previously, when the 1145 Series Key Fob was removed from the premises causing the key fob to lose communication with 1100 Series Wireless Receiver and then returned, the key fob attempted to re-establish communication with the receiver only if a button was pressed. If the key fob had been programmed with a supervision check in time and no buttons were pressed the panel may have falsely reported the key fob as missing. Key fob operation has been enhanced to automatically attempt to communicate with the receiver every four hours to avoid false missings.

Obtaining the New Software

To update to the latest software, return the 1145 Series Key Fob to DMP and simply indicate "Update to Latest Version Software" on the RMA tag. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

REPAIR AUTHORIZATION

DO NOT SEND METAL CABINETS WITH CIRCUIT BOARD

157668

PRINT CLEARLY THIS IS YOUR RETURN SHIPPING DOCUMENT.

Company ALAN CO. NAME

Address ADDRESS

City _____ State _____ Zip _____

Model No. MODEL S/N _____

Installation Site _____

Describe Problem UPDATE TO LATEST SOFTWARE

Preferred return shipping method _____

FOR DMP USE ONLY

Received _____ By _____ Code _____

Bench Test _____ In-Circuit Test _____ Functional Test _____

Repaired _____ By _____ Code _____

Parts Replaced _____ By _____ Code _____

☐ PCB ☐ Housing ☐ Box ☐

Final Test _____ By _____

Shipped _____ By _____

Data Entry _____ By _____

KEEP THIS STUB FOR YOUR RECORDS

Repair Voucher

Model No. _____ S/N _____

Installation Site _____

157668