

## 1145 Series Wireless Key Fobs March 2010

### Version 106 Update

Effective March 2010, all 1145, 1146 and 1147 Wireless Key Fobs are being manufactured as Version 106 (3/10/10) software. This version is an update from the Version 106 (11/10/08) software previously shipped and contains updated operation.

### Updated Operation

#### Improved Battery Life

The communication process of a wireless key fob has been improved to further battery life. During the period when the key fob has been removed from the premises causing a loss of communication with the receiver, key fob communication attempts to find the wireless receiver are reduced to conserve the battery.

### Ordering the New Software

To update the software in an existing 1145, 1146 or 1147 Wireless Key Fob, return the key fob to DMP and simply indicate "Update to Version 106" on the 6-digit RMA tag. This update will be done automatically as a standard part of the repair. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

