

1100D Wireless Receivers December 2008

Version 106 Update

Effective December 2008 all 1100D, 1100DI and 1100DH Wireless Receivers are being manufactured as Version 106 (11/25/08) software. This version is an update from the Version 106 (10/31/08) software previously shipped and contains updated operation.

Updated Operation

Wireless Outputs

When wireless outputs such as an 1116 or 1117 were operating within range of an 1100R repeater, but out of range of the 1100D receiver, the output could not be turned on using Remote Link or System Link. Outputs could always be turned on using the keypad or by options set in the panel.

Ordering the New Software

To update the software in an existing 1100 Series Wireless Receiver, return the receiver to DMP and simply indicate "Update to Version 106" on the 6-digit RMA tag. The update will be done under warranty at no charge, regardless of when the receiver was purchased. If a receiver is returned for other repair needs, this update will be done automatically as a standard part of the repair. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

