

## 1114, 1116, 1117 and 1118 Software Update September 2008

### Version 100 Software Update

Effective September 2008, all 1114 Wireless Zone Expanders and the 1116, 1117 and 1118 Wireless Modules are being manufactured with Version 100 (9/8/08) software. This new version will begin shipping once existing versions are depleted from stock. This version is an update from the Version 100 (5/1/08) software previously shipped and contains updated operation.

### Updated Operation

#### Battery Life Improved

The new Version 100 (9/8/08) software further improves the battery life of the 1114, 1116, 1117 and 1118 wireless modules. Most 1114, 1116, 1117 and 1118 modules manufactured since May of 2008 operate with the normal battery life expectancy. However, in a few cases, the processor operation could shorten battery life. This typically occurred when the module was unable to communicate with the 1100 Series Wireless Receiver. An indication of trouble would be a low battery or an unexpected missing message at the keypad.

### Receiving New Software

To update the software in an existing 1114, 1116, 1117 or 1118, return the module to DMP and simply indicate "Update to Current Version" on the RMA tag. The update will be done as a Warranty Repair at no charge, regardless of when the module was purchased. If a module is returned for other repair needs, this update will be done automatically as a standard part of the repair. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

