

FEATURE UPDATE | JULY 2021

Version 201 (7/2/21) Update

Effective July 19, 2021, all 1100T Series Wireless Translators are being manufactured with Version 201 (7/2/21) firmware.

Expanded Sensor Abilities

The Interlogix® 802A Shock Sensor now works with 1100T units using Version 201 (7/2/21). For more information about other compatible devices, see the [1100T Wireless Translator Compatibility Guide](#).

Easier Programming

This update also allows Interlogix device contacts to be easier to program. Contact 1 is still mapped to the expected location of the zone information of each device. However, if after trying to program an untested device and contact 1 does not work, use the other three contacts provided.

Obtaining the New Firmware

New 1100T Series Wireless Translators Version 201 (7/2/21) can be ordered by contacting DMP Customer Service at 1-866-266-2826 or by visiting buy.dmp.com.