



TECHNICAL UPDATE | FEBRUARY 2021

Version 711 Date Code Update

Version 711 (2/9/21) firmware is now available on Dealer Admin (dealer.securecomwireless.com) or for download at DMP.com/Dealer_Direct.

Improvements

Bad Zone State Enhancement

Previously, the XR INT Series panel processed a single bad zone state as an alarm or trouble message. With updated Version 711 (2/9/21) firmware, the panel requires three bad zone states before processing an alarm or trouble message.

Obtaining the New Firmware

Version 711 (2/9/21) firmware is now available for download at DMP.com/Dealer_Direct.