SCS-105 Firmware Update
February 2009

Version 208 Firmware Update

Effective February 2009, all SCS-105 SDLC Single Line Service Receivers are being manufactured with Version 208 (1/28/09) firmware. This version is an update from the version 208 (6/25/07) firmware previously available and contains updated operation.

Updated Operation

Requesting Events

The SCS-105 SDLC Single Line Service Receiver now has extended timing delays to allow proper communication when using public switched telephone systems that have long internal delays.

Upgrading/Ordering New Firmware

SCS-105 Version 208 (1/28/09) firmware PROMs may be purchased by calling DMP Customer Service at 1-800-641-4282.