TECHNICAL UPDATE

1145 Series Wireless Key Fob
October 2011

Version 107 Software Update

Effective October 14, 2011 all 1145 Series Wireless Key Fobs are being manufactured with Version 107 (7/07/11) software. As of October 14, 2011, inventory for the 1145-4 (four button) Series Key Fobs will be completely updated to Version 107 (7/07/11) software. This new software will begin shipping in 1145-1 (one button) and 1145-2 (two button) key fobs by the end of October.

Updated Operation

Enhanced Noise Immunity

The 1145 Series Key Fobs now provide enhanced immunity to radio frequency (RF) noise. Environmental RF noise occurs when AC electrical devices are turned on and off. Previously, RF noise could cause the key fob to intermittently activate the wireless radio in preparation for radio communication reducing battery life.

Low Battery testing

The 1145 Series Key Fob now reports a low battery condition in a more timely manner by automatically testing for a low battery on a daily basis.

Previously, the low battery test was based on a set number of button presses to trigger a low battery report.

Obtaining the New Software

To update, return any older 1145 Series Wireless Key Fob to DMP and simply indicate "Update to Latest Version 107 Software" on the RMA tag. The update will be done as a Warranty Repair at no charge, regardless of when the key fob was purchased. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

Software Version
The software version of an 1145 is found by removing the back cover of the key fob.

DMP
Digital Monitoring Products