Remote Link and System Link
November 2007

Version 1.40 Software Update

Effective December 2007, all Remote Link and System Link software is being manufactured as Version 1.40 (11/27/07). This version is an update from the Version 1.38 (9/27/07) previously shipped and contains updated operations.

Updated Operation

Remote Update

Remote Link now correctly converts an XR500 file version 119 (5/4/07) to the version 120 (9/27/07) when remotely updating an installed panel.

Previously, Remote Link would occasionally stop responding when connecting to the XR500 Version 120 (9/27/07) panel for the first time after the remote update was performed. The user would need to create a new XR500 version 120 file to then allow a connection to the panel.

Panel Event Buffer Report

Remote Link no longer indicates an Access Violation when a user closes the report preview window.

Previously, when a Panel Event Buffer report was opened in the preview mode while connected to a panel and then left open on the screen until the panel automatically disconnected, an Access Violation would occur when the user attempted to close the report preview window.

DBISAM Update

This version of Remote Link includes an update to the DBISAM database engine to version 4.25 build 6. This DBISAM update fixes some minor database issues, none of which are known to cause problems with Remote Link.

Obtaining the New Software

Remote Link and System Link updates version 1.40 are available for download free of charge on the DMP Dealer Direct Website at http://dmp.com/dealer. Hard copy updates on CD can be obtained from buy.dmp.com or by calling DMP Customer Service at 1-800-641-4282.

DMP
Digital Monitoring Products