Firmware Update
March 2008

Version 108 Firmware Update for Older XR20 Panels

A new firmware update is available for XR20 Command Processor panels built between April 1996 and July 2000 on PC-0027. This version 108 (3/3/08) firmware is an update from the Version 108 (5/15/02) firmware previously available and contains updated operation.

Updated Operation

Time Display

It is possible that the Time display feature at the keypad would stop operating after 10 years of panel operation. If this occurred, the issue would appear as one of the following:

- The time display was always wrong.

- The time display is out-of-range numbers.

- The panel would randomly go in and out of schedule

This update will use the EEPROM memory for time storage in a revised manner that corrects this issue.

Upgrading/Ordering New Firmware

New firmware PROMs may be purchased from buy.dmp.com or by calling DMP Customer Service at 1-800-641-4282. All panels returned for repair are automatically updated to the latest firmware.

Note: Version 108 firmware is only for use with the PCB PC-0027 hardware. PCB PC-0027 hardware has not been manufactured since July 2000. The PCB designation is located at the top right of the PCB.