XR100 and XR500 Series
July 2009

Version 203 Software Update

Effective July 2009, all XR100 and XR500 Series Command Processor™ panels are being manufactured with Version 203 (7/2/09) software. This version is an update from the Version 203 (5/1/09) software previously shipped and contains updated operation.

Updated Operation

893A Alternate Daily Test

When using the 893A, the XR100/XR500 panel alternates between Phone Line 1 to Phone Line 2 each time the Automatic Recall test message is sent to the receiver.

Previously, the panel sent the Automatic Recall message was only sent on Phone Line 1.

Early Morning Ambush CID Message

The XR100 and XR500 now send the CID message E121 when an Early Morning Ambush occurs.

Previously, a panel using any software from version 200 to version 203 (5/1/09) that was programmed for CID communication and using the Early Morning Ambush operation did not send CID message E121 to the receiver.

DMP strongly recommends that any panel programmed for CID communication and using the Early Morning Ambush operation and currently using any software from version 200 to version 203 (5/1/09) be updated to version 203 (7/2/09).

This issue does not occur in panels using software version 121 or lower or panels that do not use CID communication.

Remote Programming Complete

The message Remote Programming Complete (System Message 83) is now only sent to the receiver when actual programming changes were made during the remote session that had just ended.

Previously, System Message 83 was sent after every remote connection regardless if any changes were made to programming.

Obtaining the New Software

XR100 and XR500 Series software update Version 203 (7/2/09) is available for download free of charge on the DMP Dealer Direct Website at http://dmp.com/dealer.

Digital Monitoring Products