XR100 and XR500 Series
May 2010

Version 205 Software Update

Effective May 2010, all XR100 and XR500 Series Command Processor™ panels are being manufactured with Version 205 (5/13/10) software. This version is an update from the Version 205 (1/5/10) software previously shipped and contains updated operations.

Updated Operations

Panel Upgrade

On occasion when updating a panel to Version 205 (1/5/10) from a much older version of software such as Version 119, the panel's communication programming could be changed. This caused panel communication to cease and a loss of connectivity with Remote Link until the panel was manually reprogrammed.

This issue could only occur while updating a panel software version and occurred much less often if the panel version being updated was newer. Panels that have been successfully updated or are already operating with Version 205 (1/5/10) are not affected and do not need to be updated to Version 205 (5/13/10).

Remote Link & User Names

When using an older version of Remote Link (1.49 or older), the panel could not correctly read the user name of a user code sent from Remote Link. The user name would appear in the panel as other characters.

This issue does not occur when using any version of Remote Link newer than version 1.49 such as Version 1.50 or higher.

Low Battery Testing

The XR100 and XR500 Series panels now extend the amount of time required to detect a low battery condition during the five second battery test.

Previously, when testing the battery, only a short period was used to detect a low battery and on very rare occasions, a false low battery condition was indicated for three minutes until the next battery test.

Obtaining the New Software

XR100 and XR500 Series software updates are available for download free of charge on the DMP Dealer Direct Website at http://dmp.com/dealer.

Digital Monitoring Products