TECHNICAL UPDATE

SCS-104 Receiver Line Card
May 2013

Version 101 Software Update

SCS-104 Version 101 (5/9/13) software is now available for download on the DMP Dealer Direct Website at http://dmp.com/dealer.

Effective 5/24/13, all SCS-104 Receiver Line Cards will be manufactured and with Version 101 (5/9/13) software.

Updated Operation

Outgoing Dialer Timeout

When using an SCS-104 to dial out to a panel, the SCS-104 would hang up if the panel did not answer within 40 seconds. Version 101 (5/9/13) now hangs up after 90 seconds to allow more time to establish connections with panels that have a high number of Armed/Disarmed Answer Rings programmed.

Obtaining the New Software

SCS-104 software updates are available for download free of charge on the DMP Dealer Direct Website at http://dmp.com/dealer.

The SCS-104 can be updated using Remote Link Version 1.61 or higher and a Model 399 Programming Cable. See the SCS-104 Installation Sheet (LT-1207) for more information.