Version 191 Firmware Update

Version 191 (5/29/19) firmware is now available on DMPDealerAdmin.com or for download at DMP.com/Dealer_Direct.

The following features are available.

Features

⊕ **Instant Zone Type**

With Version 191 (5/29/19), a new Instant zone type can be found in **Zone Information**. The Instant zone type does not follow the entry or exit delay of its assigned area. If the zone is tripped during the entry/exit delay, the alarm will be triggered instantly.

⊕ **System Analytics**

XT Version 191 (5/29/19) has been updated to send hourly cell signal and cell tower ID's to Dealer Admin. You can use this feature to more precisely troubleshoot cellular communication issues.

⊕ **Zone Bypass and Restoration**

Version 191 (5/29/19) firmware gives visual confirmation when a zone has been bypassed or restored from the keypad.

⊕ **TCP Source Port Improvement**

Previously after updating to XT 191 (4/16/19), a random source port could be chosen that was lower than the panels programming port. Once the source port advanced to the panels programming port, a port conflict could occur. XT 191 (5/29/19) has been updated to exclude the panels programming port from the TCP source port.

Supporting Software Updates

- **Dealer Admin Version 2.16.3** - Dealer Admin Version 2.16.3 now supports the Instant zone type and System Analytics.
- **Tech App Version 2.2.3** - Tech App Version 2.2.3 now supports the Instant zone type.

Obtaining the New Firmware

XT Series firmware updates are available, free of charge, at DMPDealerAdmin.com or DMP.com/Dealer_Direct.