SCS-VR
December 2011

Version 1.3.5 Software Update

Effective December 2011, all SCS-VR Virtual Receivers are being manufactured as Version 1.3.5 (12/1/11).

Updated Operation

Clear Database

The Clear Database function initiated from the SCS-VR computer now always completes successfully.

Previously, when Clear Database was selected from the SCS-VR computer and the database was stored on a separate remote computer, the operation to clear and create a new database would not always complete if there were any network latency issues.

This issue did not occur when Clear Database was selected and the database was on the same computer.

Delete Panel

SCS-VR now only allows panels that have failed to communicate within the programmed check-in time to be deleted from the list of panels that are currently communicating with SCS-VR and displayed in the Panels tab.

Previously, SCS-VR allowed panels that had not been reported as Panel Not Responding (S16) to be deleted.

Panel Response Restored (S17)

When a panel sends a check-in message for the first time, SCS-VR now correctly sends a Panel Response Restored (S17) message to Host Automation instead of a New Panel On Line (S19).

Log Default

The SCS-VR configuration file, logging.conf, now defaults to WARN instead of ALL for logging transactions between SCS-VR and host automation.

Ordering New Firmware

SCS-VR Version 1.3.5 update will be automatically provided to dealers who have previously purchased an SCS-VR license and are current with their SCS-VR support agreement.