TECHNICAL UPDATE

XR100 and XR500 Series
May 2008

Version 121 Software Update

Effective May 2008, all XR100 and XR500 Series Command Processor panels are being manufactured with Version 121 (5/9/08) software. This version is an update from the Version 121 (2/15/08) software previously shipped and contains updated operation.

Updated Operation

Zone Delay

The time required to recognize that a keypad bus or panel zone is either open or short has been reduced from 1 second to 500 milliseconds. The Fast Response programming option, which further reduces the zone response time to 167 milliseconds, continues to be available in Zone Information programming.

Obtaining the New Software

XR100 and XR500 Series software update Version 121 (5/9/08) is available for download free of charge on the DMP Dealer Direct Website at http://dmp.com/dealer.

DMP
Digital Monitoring Products