XRSuper6, XR20 and XR40 Firmware Update
March 2008

Version 306 Firmware Update

Effective April 2008, all XRSuper6, XR20 and XR40 Command Processor panels are being manufactured with version 306 (3/14/08) firmware. This version is an update from the version 306 (9/24/07) firmware previously available and contains updated operation.

Updated Operation

Extended Schedule

It was possible that the Extend Schedule feature would stop operating properly after 5 – 10 years of panel operation. If this occurred, the issue would appear as one of the following:

- The panel schedule could never be extended.

- The panel schedule was always extended and always in schedule.

- The panel could go in and out of schedule

This update will use the EEPROM memory in a revised manner that corrects this issue.

Upgrading/Ordering New Firmware

New firmware PROMs may be purchased from buy.dmp.com or by calling DMP Customer Service at 1-800-641-4282. All panels returned for repair are automatically updated to the latest firmware.